-		A
	H	\mathcal{A}
No.	138	
	E	EP

United States Environmental Protection Agency Washington, D.C. 20460

Water Compliance	e inspection Rep	ort	
Section A: Nation	nal Data System Coding (i.	e., PCS)	
Transaction Code NPDES 1 [씨 [씨유띠이이이3 8 4]	yr/mo/day 1 3 0 2 1 3 Remarks	Inspection Type	Inspector Fac Type
21 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			6
Inspection Work Days Facility Self-Monitoring Evaluation Rating 67 69 70 70	BI QA 71 72 7	73	Reserved5
Sei	ction B: Facility Data		
Name and Location of Facility Inspected (For industrial users discinclude POTW name and NPDES permit number) Robert J Smit Dairy	harging to POTW, also	Entry Time/Date 2/13/13	Permit Effective Date
9039 Guide Meridian Road Lynden, WA 98264		Exit Time/Date 2/13/13	Permit Expiration Date
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Nun Robert Smit, Owner (b) (6)	nber(s)	1750 1070, 1070	g., SIC NAICS, and other
Name, Address of Responsible Official/Title/Phone and Fax Numb Robert Smit, Owner, (b) (6) 9039 Guide Meridian Road Lynden, WA 98264 Section C: Areas Evaluated Duri Permit Self-Monitoring Pr Records/Reports Compliance Scheol	Contacted Yes No No Ing Inspection (Check only rogram Pretreatment dules Pollution Pre	MS vention	
Effluent/Receiving Waters Operations & Mair Flow Measurement Sludge Handling/D	Disposal Sanitary Sew		
Section D: Su (Attach additional sheets of narrative and che	immary of Findings/Comme ecklists, including Single E		as necessary)
SEV Codes SEV Description		RECEIVE	D
		FEB 2 7 20	13
• • • • • • •	Insp	ection & Enforcement Ma (IEMU)	anagement Unit
Name(s) and Signature(s) of Inspector(s) Sandra Brozusky	Agency/Office/Phone and Fa EPA OCE 206-553-5317		Date 2/26/13
Matt Vojik	-EPA OCE 206-553-0716		
Signature of Management Q A Reviewer	Agency/Office/Phone and Fax Numbers Date		

EPA Form 3560-3 (Rev 1-06) Previous editions are obsolete.

ICIS. 2-28-2013 MBrown

INSTRUCTIONS

Section A: National Data System Coding (i.e., PCS)

Column 1: Transaction Code: Use N. C. or D for New, Change, or Delete. All inspections will be new unless there is an error in the data entered.

Columns 3-11: NPDES Permit No. Enter the facility's NPDES permit number - third character in permit number indicates permit type for U=unpermitted, G=general permit, etc.. (Use the Remarks columns to record the State permit number, if necessary.)

Columns 12-17: Inspection Date. Insert the date entry was made into the facility. Use the year/month/day format (e.g., 04/10/01 = October 01, 2004).

Column 18: Inspection Type*. Use one of the codes listed below to describe the type of inspection:

A	Performance Audit	U	IU Inspection with Pretreatment Audit	1	Pretreatment Compliance (Oversight)
В	Compliance Biomonitoring	X	Toxics Inspection	@	Follow-up (enforcement)
C	Compliance Evaluation (non-sampling)	Z	Sludge - Biosolids	(C)	Tollow up (criticiocriticity)
D	Diagnostic	#	Combined Sewer Overflow-Sampling	{	Storm Water-Construction-Sampling
F	Pretreatment (Follow-up)	\$	Combined Sewer Overflow-Non-Sampling		
G	Pretreatment (Audit)	+	Sanitary Sewer Overflow-Sampling	}	Storm Water-Construction-Non-Sampling
I	Industrial User (IU) Inspection	&	Sanitary Sewer Overflow-Non-Sampling		Storm Water-Non-Construction-Sampling
J	Complaints	1 -	CAFO-Sampling		and the second of the second o
M	Multimedia	=	CAFO-Non-Sampling	~	Storm Water-Non-Construction-
N	Spill	2	IU Sampling Inspection		Non-Sampling Storm Water-MS4-Sampling
0	Compliance Evaluation (Oversight)	3	IU Non-Sampling Inspection	-	
P	Pretreatment Compliance Inspection	4	IU Toxics Inspection	-	Storm Water-MS4-Non-Sampling
R	Reconnaissance	5	IU Sampling Inspection with Pretreatment	>	Storm Water-MS4-Audit
S		6	IU Non-Sampling Inspection with Pretreatment		
0	Compliance Sampling	7	IU Toxics with Pretreatment		

Column 19: Inspector Code. Use one of the codes listed below to describe the lead agency in the inspection.

A 100%	
A — State (Contractor) B — EPA (Contractor) E — Corps of Engineers J — Joint EPA/State Inspectors—EPA Lead L — Local Health Department (State) N — NEIC Inspectors	 O— Other Inspectors, Federal/EPA (Specify in Remarks columns) P— Other Inspectors, State (Specify in Remarks columns) R— EPA Regional Inspector S— State Inspector T— Joint State/EPA Inspectors—State lead

Column 20: Facility Type. Use one of the codes below to describe the facility.

- 1 Municipal. Publicly Owned Treatment Works (POTWs) with 1987 Standard Industrial Code (SIC) 4952.
- 2 Industrial. Other than municipal, agricultural, and Federal facilities.
- Agricultural. Facilities classified with 1987 SIC 0111 to 0971 3-
- Federal. Facilities identified as Federal by the EPA Regional Office.
- Oil & Gas. Facilities classified with 1987 SIC 1311 to 1389.

Columns 21-66: Remarks. These columns are reserved for remarks at the discretion of the Region.

Columns 67-69: Inspection Work Days. Estimate the total work effort (to the nearest 0.1 work day), up to 99.9 days, that were used to complete the inspection and submit a QA reviewed report of findings. This estimate includes the accumulative effort of all participating inspectors; any effort for laboratory analyses, testing, and remote sensing; and the billed payroll time for travel and pre and post inspection preparation. This estimate does not require detailed

Column 70: Facility Evaluation Rating. Use information gathered during the inspection (regardless of inspection type) to evaluate the quality of the facility self-monitoring program. Grade the program using a scale of 1 to 5 with a score of 5 being used for very reliable self-monitoring programs, 3 being satisfactory, and 1 being used for very unreliable programs.

Column 71: Biomonitoring Information. Enter D for static testing. Enter F for flow through testing. Enter N for no biomonitoring.

Column 72: Quality Assurance Data Inspection. Enter Q if the inspection was conducted as followup on quality assurance sample results. Enter N otherwise

Columns 73-80: These columns are reserved for regionally defined information.

Section B: Facility Data

This section is self-explanatory except for "Other Facility Data," which may include new information not in the permit or PCS (e.g., new outfalls, names of receiving waters, new ownership, other updates to the record, SIC/NAICS Codes, Latitude/Longitude).

Section C: Areas Evaluated During Inspection Enlopcement Management Unit

Check only those areas evaluated by marking the appropriate box. Use Section D and additional sheets as necessary. Support the findings, as necessary, in a brief narrative report. Use the headings given on the report form (e.g., Permit, Records/Reports) when discussing the areas evaluated during the inspection

Section D: Summary of Findings/Comments

Briefly summarize the inspection findings. This summary should abstract the pertinent inspection findings, not replace the narrative report. Reference a list of attachments, such as completed checklists taken from the NPDES Compliance Inspection Manuals and pretreatment guidance documents, including effluent data when sampling has been done. Use extra sheets as necessary.

*Footnote: In addition to the inspection types listed above under column 18, a state may continue to use the following wet weather and CAFO inspection types until the state is brought into ICIS-NPDES: K: CAFO, V: SSO, Y: CSO, W: Storm Water 9: MS4. States may also use the new wet weather, CAFO and MS4 inspections types shown in column 18 of this form. The EPA regions are required to use the new wet weather, CAFO, and MS4 inspection types for inspections with an inspection date (DTIN) on or after July 1, 2005.

Park Contract Condition